

Incoming  
m/043/0019  
cc:cesie 0001

**STATE OF UTAH**  
DEPARTMENT OF NATURAL RESOURCES  
**DIVISION OF OIL, GAS AND MINING**  
1594 West North Temple - Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801  
Telephone: (801) 538-5291  
Fax: (801) 359-3940

**LARGE MINING OPERATIONS 2009 PROGRESS REPORT**  
**January 1, 2009 to December 31, 2009**

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: M/043/019
2. Mine Name: Mountain Valley Stone
3. Name of Operator/Permittee: Robert Hicken

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention together with form MR-REV available on the Division's web page at [https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR-REV.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-REV.pdf).

4. Mine Location: Browns Canyon Poca, Utah
5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):

Gross Ore Mined 84,457.8 Tons, or \_\_\_\_\_ yd<sup>3</sup>  
 Waste Material Moved 0 Tons, or \_\_\_\_\_ yd<sup>3</sup>  
 New Disturbance 0 Acres during 2009  
 Area Reclaimed 0 Acres during 2009  
 Total Disturbed Area 33 Acres\*

\*Total mine disturbance from the beginning of mining operations through the end of 2009.

Was the ore shipped off site? If not, where is the ore located? Yes, the ore was divided into products and sold.  
 Where is the waste located? The overburden was crushed and sold as sand and gravel.

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE ([https://fs.ogm.utah.gov/pub/mines/minerals\\_related/forms/MR-SITE.pdf](https://fs.ogm.utah.gov/pub/mines/minerals_related/forms/MR-SITE.pdf)) to apply for full or partial bond/site release).  
No reclamation work was done. No map is included because no additional or different work has been done.
7. For large mines, include an updated map depicting surface disturbance and reclamation performed during the year (Rule R647-4-105).

**I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.**

Name (Typed or Print): Robert Hicken  
 Title of Operator: Owner  
 Signature of Operator: [Signature]  
 Date: 1/25/10